

## Wick Community Council Survey of benches Report, January 2021:



### **Bench 1, St Brides Road, near the bus stop.**

This bench is in a poor condition with a missing back support slat. The remainder of the wood urgently needs treating to restore it to an acceptable standard.



### **Bench 2, Outside Village School**

This bench is in a reasonable condition, but the wood needs treating to preserve it.



### **Bench 3 Church Street**

This bench is also in poor condition with a missing slat. The remaining slats are in encrusted and need treating to maintain and preserve them.



### **Bench 4 and 5, metal edged benches on Village Green**

These benches are in a reasonable condition although the wooden slats need treating to preserve them.



**Bench 6, Stone edged bench, Village Green**

The wooden back and seat of this bench has started to rot, it needs remedial work or replacement.



**Bench 7, Playground, Village Green**

This bench is deteriorating, it has a missing seat slat and the remaining slats require cleaning and treatment to preserve them.



**Picnic Bench 8, near new MUGA at Sports Pavilion**

The bench is in a poor state of repair with one of its four seats missing.

**Bench 9 and 10, Memorial Benches**

There are two other benches on the village green. We understand they are privately owned and are not included in the survey.

**Bench 11, Broughton Road**

There is a bench half way down Broughton Road that is set back from the road. The area is overgrown and nothing remains of the bench except the concrete supports.